MATERIAL SAFETY DATA SHEET

Identity (As Used on Label and List) Emergency/Info.Telephone # Dermagran Wound Cleanser with Zinc WC-OH (800) - 346 - 7197Date Prepared:11/15/95 Section I - Manufacturer (Name / Address) Ambix Lab 15 Hampshire Street Mansfield, MA 02048 ACGIH TLV OSHA PEL Section II- Hazardous ingredients/identity inform. 5 1000PPM 1000PPM SDA Alcohol 40-2 Section III-Physical/Chemical Characteristics Specific Gravity $(H^2O = 1)$ Boiling Point = 173º F* 0.816@60°F Melting Point Vapor Pressure (mm Hg.) -173°F* @68°F* 44.6mmHg Evaporation Rate Vapor Density (air = 1) (Butyl Acetate = 1) Solubility in Water COMPLETE Appearance & Odor CLEAR, COLORLESS Section IV - Fire and Explosion Hazard Data Flammable Limits Flash Point (method used) UEL LEL 62° F* ASTM D-56 19* 3.3* Extinguishing Media

Dry chemical, "Alcohol" Foam

Carbon Dioxide

MATERIAL SAFETY DATA SHEET

Special Fire Fighting
Procedures - Self contained
breathing Apparatus* and
Spray onto fire. Cool. Other
flammable containers with
cold water.

Unusual Fire and Explosion Hazards: Use self-contained apparatus in positive pressure mode.*

Section V - Reactivity Data

Contact wit Stability - Stable - X and Oxidizin

Incompatibility(materials to avoid) See Conditions

Conditions to Avoid Contact with Acetyl Chloride
and Oxidizing Agents *

Hazardous Decomposition or
Byproducts - Carbon Monoxide
can form in incomplete
combustion.*

Hazardous Polymerization

Conditions to Avoid -

May Occur - Will not Occur -

Section VI - Health Hazard

Data

Routes of Entry: Check all that apply

Health Hazards (acute &
chronic)

Inhalation - X Skin - X Ingestion - X Inhalation over 1000ppm may cause headache, drowsiness, loss of appetite. Ingestion CNS depression, nausea, vomiting, diarrhea, skin irritation and defatting of skin.

Carcinogenicity
NTP
IARC Monographs
OSHA Regulated
Medical Conditions generally
aggravated by Exposure

Signs and Symptoms of Exposure: SEE ABOVE

Emergency & First Aid Procedures: Remove to fresh air if inhaled. Dilute with fluids if ingested. Flush skin with water if contacted.*

Section VII - Precautions for Safe Handling and Use

Steps to be taken in case

Waste Disposal Method:

MATERIAL SAFETY DATA SHEET

spilled: Handle with adequate with water. ventilation.* Wear protective clothing/gloves, wear safety glasses.

material is released or Spills should be diluted

Precautions to be taken in handling and storage : See HANDLING ABOVE

Other Precautions: NONE

Section VIII - Control

Measures

Respiratory Protection (Specify Type)

Ventilation

Local Exhaust : X Special : Mechanical Other

Use in well-ventilated area

Protective Gloves : X Eye Protection : X

Other Protective Clothing or Equipment: NONE

Work/hygienic Practices: Use normal cautions

* For pure ethyl alcohol